

## ASBESTOS MATERIALS

The following materials either tested positive or are presumed to be asbestos-containing. Materials that had mixed results are considered positive. Materials not sampled may contain asbestos and should be tested to verify asbestos content prior to impact, demolition, renovation, etc.

(+) Tested Positive, (M) Mixed Results, (P) Presumed Positive

Buff Elementary School (BES)			
Result	Material	Location	Quantity
P	4" Brown Covebase and Mastic	Throughout school	
P	Wall and Ceiling Plaster	Throughout school	
P	Grey Textured Sink Undercoating	Various classrooms	
P	12" x 12" Vinyl Floor Tile and Mastic	Various classrooms and hallways	
P	2' x 4' Lay-in Ceiling Tile	Various hallways and classrooms	
P	Glued-on Ceiling Tiles	Various hallways and classrooms	
P	Vinyl Sheet Floor Covering (Tan and Blue)	Various hallways and kitchen	

## MATERIALS THAT TESTED NEGATIVE FOR ASBESTOS

The following materials tested negative. Although no asbestos was detected, it is possible that further sampling could indicate asbestos content. It may be prudent to test prior to impact, demolition, renovation, etc.

## ASBESTOS SUMMARY

July 2021	<p><b>Project Number:</b> #</p> <p><b>Activity Type:</b> Reinspection</p> <p><b>Activity Name:</b> 2021 - AHERA Reinspection</p> <p><b>Location:</b> Throughout</p> <p><b>Description:</b></p> <p><b>Related Documents:</b> Yes</p>
July 2023	<p><b>Project Number:</b> BES2023-2</p> <p><b>Activity Type:</b> Periodic Surveillance</p> <p><b>Activity Name:</b> July 2023 Periodic Surveillance</p> <p><b>Location:</b> Buff Elementary School</p> <p><b>Description:</b></p> <p><b>Related Documents:</b> Yes</p>