

ASBESTOS MATERIALS

The following materials either tested positive or are presumed to be asbestos-containing. Materials that had mixed results are considered positive. Materials not sampled may contain asbestos and should be tested to verify asbestos content prior to impact, demolition, renovation, etc.

(+) Tested Positive, (M) Mixed Results, (P) Presumed Positive

District Office (DO)			
Result	Material	Location	Quantity
P	Glued-on Ceiling Tiles	Board room	
P	Gypsum and Plaster Walls and Ceilings	Throughout district office	
P	Orange Peel Textured Wall Material	Throughout district office	
P	6" Black Covebase and Mastic	Throughout maintenance shop office	
P	Wall and Ceiling Plaster	Throughout maintenance shop office	
P	Pink Sink Undercoating	Various bathrooms and offices	
P	12" x 12" Blue Vinyl Floor Tile and Mastic	Various offices	
P	Black Textured Sink Undercoating	Various offices	
P	Sheet Floor Covering (various colors)	Various offices	
P	Sheet Floor Covering	Various offices and rest rooms of maintenance shop office	

MATERIALS THAT TESTED NEGATIVE FOR ASBESTOS

The following materials tested negative. Although no asbestos was detected, it is possible that further sampling could indicate asbestos content. It may be prudent to test prior to impact, demolition, renovation, etc.

ASBESTOS SUMMARY

July 2021	<p>Project Number: #</p> <p>Activity Type: Reinspection</p> <p>Activity Name: 2021 - AHERA Reinspection</p> <p>Location: Throughout</p> <p>Description:</p> <p>Related Documents: Yes</p>
July 2023	<p>Project Number: DO2023-2</p> <p>Activity Type: Periodic Surveillance</p> <p>Activity Name: July 2023 Periodic Surveillance</p> <p>Location: District Office</p> <p>Description:</p> <p>Related Documents: Yes</p>