

ASBESTOS MATERIALS

The following materials either tested positive or are presumed to be asbestos-containing. Materials that had mixed results are considered positive. Materials not sampled may contain asbestos and should be tested to verify asbestos content prior to impact, demolition, renovation, etc.

(+) Tested Positive, (M) Mixed Results, (P) Presumed Positive

Bridges High School (BHS)			
Result	Material	Location	Quantity
P	Asbestos Pipe Insulation	Boiler room and possibly concealed in wall voids, attics, or tunnels.	
P	9" x 9" Tan Vinyl Floor Tile and Mastic	Gymnasium	
P	Glued-on Ceiling Tiles with Brown Mastic Dots	Throughout school	
P	Wall Plaster	Throughout school	
P	Acoustical Wall Tile and Mastic	Various classrooms	
P	Tan Mosaic Sheet Floor Covering	Various classrooms	
P	Textured Sink Undercoating (Black and Grey)	Various classrooms	
P	White Speckled Sheet Floor Covering	Various classrooms	
P	2' x 4' Lay-in Ceiling Tile	Various classrooms and hallways	
P	9" x 9" Brown Vinyl Floor Tile and Mastic	Various classrooms and hallways	

MATERIALS THAT TESTED NEGATIVE FOR ASBESTOS

The following materials tested negative. Although no asbestos was detected, it is possible that further sampling could indicate asbestos content. It may be prudent to test prior to impact, demolition, renovation, etc.

ASBESTOS SUMMARY

July 2021 **Project Number:** #
Activity Type: Reinspection
Activity Name: 2021 - AHERA Reinspection
Location: Throughout
Description:
Related Documents: Yes

July 2023 **Project Number:** BHS2023-2
Activity Type: Periodic Surveillance
Activity Name: July 2023 Periodic Surveillance
Location: Bridges High School
Description:
Related Documents: Yes