

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Madras High School	Main Building	A102	12/14/2020	Detector kit	1.2
Madras High School	Main Building	RECEPTION	12/14/2020	Detector kit	0.6
Madras High School	Main Building	WORK	12/14/2020	Detector kit	0.7
Madras High School	Main Building	OFFICE	12/14/2020	Detector kit	0.6
Madras High School	Main Building	F110	12/14/2020	Detector kit	0.5
Madras High School	Main Building	F112	12/14/2020	Detector kit	0.6
Madras High School	Main Building	F102	12/14/2020	Detector kit	0.4
Madras High School	Main Building	A120	12/14/2020	Detector kit	0.4
Madras High School	Main Building	A121	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	A122	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	A123	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	A124	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	A124 DUP	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	A128	12/14/2020	Detector kit	0.4
Madras High School	Main Building	B101	12/14/2020	Detector kit	0.7
Madras High School	Main Building	B102	12/14/2020	Detector kit	0.6
Madras High School	Main Building	A129	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	A130	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	A134	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	A135	12/14/2020	Detector kit	<0.3

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Madras High School	Main Building	A131	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	A136	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	A132	12/14/2020	Detector kit	0.4
Madras High School	Main Building	A137	12/14/2020	Detector kit	0.5
Madras High School	Main Building	A133	12/14/2020	Detector kit	0.3
Madras High School	Main Building	STUDENT	12/14/2020	Detector kit	0.9
Madras High School	Main Building	STUDENT	12/14/2020	Detector kit	1.1
Madras High School	Main Building	STUDENT DUP	12/14/2020	Detector kit	1.1
Madras High School	Main Building	F128	12/14/2020	Detector kit	0.4
Madras High School	Main Building	F119	12/14/2020	Detector kit	1.1
Madras High School	Main Building	F117	12/14/2020	Detector kit	0.9
Madras High School	Main Building	F113	12/14/2020	Detector kit	1.5
Madras High School	Main Building	F125	12/14/2020	Detector kit	2.5
Madras High School	Main Building	F134	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	F134	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	F135	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	GYM	12/14/2020	Detector kit	0.7
Madras High School	Main Building	F134 DUB	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	GYM	12/14/2020	Detector kit	1.4
Madras High School	Main Building	F134 BLANK	12/14/2020	Detector kit	<0.3

Jefferson County School District Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Madras High School	Main Building	C128	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	GYM	12/14/2020	Detector kit	0.9
Madras High School	Main Building	B114	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	B113	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	B112	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	B111	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	B110	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	GYM	12/14/2020	Detector kit	0.8
Madras High School	Main Building	B106	12/14/2020	Detector kit	0.5
Madras High School	Main Building	B107	12/14/2020	Detector kit	0.4
Madras High School	Main Building	GYM	12/14/2020	Detector kit	0.9
Madras High School	Main Building	B124	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	B123	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	GYM DUP	12/14/2020	Detector kit	0.8
Madras High School	Main Building	B122	12/14/2020	Detector kit	0.4
Madras High School	Main Building	GYM DUP	12/14/2020	Detector kit	0.7
Madras High School	Main Building	B127	12/14/2020	Detector kit	0.3
Madras High School	Main Building	GYM BLANK	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	B127 DUP	12/14/2020	Detector kit	0.4
Madras High School	Main Building	COMMONS	12/14/2020	Detector kit	<0.3

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Madras High School	Main Building	B128	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	COMMONS	12/14/2020	Detector kit	0.4
Madras High School	Main Building	B129	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	B120	12/14/2020	Detector kit	0.5
Madras High School	Main Building	COMMONS	12/14/2020	Detector kit	0.6
Madras High School	Main Building	B130	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	E111	12/14/2020	Detector kit	0.5
Madras High School	Main Building	C101	12/14/2020	Detector kit	0.4
Madras High School	Main Building	E111	12/14/2020	Detector kit	0.5
Madras High School	Main Building	C102	12/14/2020	Detector kit	0.4
Madras High School	Main Building	C103	12/14/2020	Detector kit	0.4
Madras High School	Main Building	E111	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	C104	12/14/2020	Detector kit	0.8
Madras High School	Main Building	E111 DUP	12/14/2020	Detector kit	0.7
Madras High School	Main Building	C107	12/14/2020	Detector kit	0.8
Madras High School	Main Building	E111 DUP	12/14/2020	Detector kit	0.6
Madras High School	Main Building	D108	12/14/2020	Detector kit	1.2
Madras High School	Main Building	C108	12/14/2020	Detector kit	0.5
Madras High School	Main Building	C109	12/14/2020	Detector kit	0.6
Madras High School	Main Building	D108	12/14/2020	Detector kit	0.8

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Madras High School	Main Building	C141	12/14/2020	Detector kit	1.0
Madras High School	Main Building	D108	12/14/2020	Detector kit	0.9
Madras High School	Main Building	G101	12/14/2020	Detector kit	2.1
Madras High School	Main Building	C138	12/14/2020	Detector kit	0.7
Madras High School	Main Building	C134	12/14/2020	Detector kit	0.7
Madras High School	Main Building	C120	12/14/2020	Detector kit	0.5
Madras High School	Main Building	G105	12/14/2020	Detector kit	0.9
Madras High School	Main Building	C119	12/14/2020	Detector kit	0.4
Madras High School	Main Building	C133	12/14/2020	Detector kit	0.4
Madras High School	Main Building	G105	12/14/2020	Detector kit	0.9
Madras High School	Main Building	C132	12/14/2020	Detector kit	0.4
Madras High School	Main Building	G105 DUP	12/14/2020	Detector kit	0.9
Madras High School	Main Building	C127	12/14/2020	Detector kit	0.4
Madras High School	Main Building	G115	12/14/2020	Detector kit	1.6
Madras High School	Main Building	C123	12/14/2020	Detector kit	0.3
Madras High School	Main Building	SMALL GYM	12/14/2020	Detector kit	0.4
Madras High School	Main Building	G115	12/14/2020	Detector kit	1.3
Madras High School	Main Building	SMALL GYM	12/14/2020	Detector kit	0.6
Madras High School	Main Building	G115 DUP	12/14/2020	Detector kit	1.8
Madras High School	Main Building	G113	12/14/2020	Detector kit	1.8

Jefferson County School District Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Madras High School	Main Building	SMALL GYM	12/14/2020	Detector kit	0.7
Madras High School	Main Building	G113	12/14/2020	Detector kit	2.0
Madras High School	Main Building	G116	12/14/2020	Detector kit	2.2
Madras High School	Main Building	SMALL GYM DUP	12/14/2020	Detector kit	0.7
Madras High School	Main Building	SMALL GYM DUP	12/14/2020	Detector kit	0.4
Madras High School	Main Building	SMALL GYM DUP	12/14/2020	Detector kit	<0.3
Madras High School	Main Building	GYM	12/14/2020	Detector kit	0.6
Madras High School	Main Building	G105 DUP	12/14/2020	Detector kit	1.9
Madras High School	Main Building	TECH	12/14/2020	Detector kit	2.4
Madras High School	Main Building	TECH DUP	12/14/2020	Detector kit	2.1
Madras High School	Main Building	TECH BLK	12/14/2020	Detector kit	<0.3
Performing Arts Center	Main Building	MAIN	12/14/2020	Detector kit	1.3
Performing Arts Center	Main Building	BOX OFF	12/14/2020	Detector kit	1.2
Performing Arts Center	Main Building	MAIN DUP	12/14/2020	Detector kit	1.5
Performing Arts Center	Main Building	MPR	12/14/2020	Detector kit	2.9
Performing Arts Center	Main Building	MPR	12/14/2020	Detector kit	2.6
Performing Arts Center	Main Building	MPR DUP	12/14/2020	Detector kit	2.8
Performing Arts Center	Main Building	HOUSE	12/14/2020	Detector kit	2.2
Performing Arts Center	Main Building	HOUSE	12/14/2020	Detector kit	2.4
Performing Arts Center	Main Building	HOUSE	12/14/2020	Detector kit	2.3

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Performing Arts Center	Main Building	HOUSE	12/14/2020	Detector kit	2.3
Performing Arts Center	Main Building	HOUSE DUP	12/14/2020	Detector kit	2.2
Performing Arts Center	Main Building	HOUSE BLK	12/14/2020	Detector kit	<0.3
Support Services Building	Main Building	BOARD	12/14/2020	Detector kit	1.5
Support Services Building	Main Building	BOARD DUP	12/14/2020	Detector kit	1.3
Support Services Building	Main Building	STAFF	12/14/2020	Detector kit	0.9
Support Services Building	Main Building	PARTITION	12/14/2020	Detector kit	1.9
Support Services Building	Main Building	PARTITION	12/14/2020	Detector kit	2.1
Support Services Building	Main Building	PARTITION	12/14/2020	Detector kit	1.9
Support Services Building	Main Building	PARTITION BLK	12/14/2020	Detector kit	<0.3
Support Services Building	Main Building	PARTITION DUP	12/14/2020	Detector kit	2.1
Support Services Building	Main Building	PAYROLL	12/14/2020	Detector kit	2.2
Support Services Building	Main Building	ACCOUNTS PAY	12/14/2020	Detector kit	1.5
Support Services Building	Main Building	SUPER INT	12/14/2020	Detector kit	2.1
Support Services Building	Main Building	CONF	12/14/2020	Detector kit	2.4
Support Services Building	Main Building	MAIL	12/14/2020	Detector kit	2.0
Support Services Building	Main Building	MAIL DUP	12/14/2020	Detector kit	2.0
Support Services Building	Main Building	OFFICE	12/14/2020	Detector kit	1.7
Support Services Building	Main Building	OFFICE	12/14/2020	Detector kit	1.9
Support Services Building	Main Building	OFFICE	12/14/2020	Detector kit	1.8

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Support Services Building	Main Building	PARTITION	12/14/2020	Detector kit	2.3
Madras Elementary	Main Building	BASEMENT	12/14/2020	Detector kit	1.1
Madras Elementary	Main Building	TEACHERS L.	12/14/2020	Detector kit	1.0
Madras Elementary	Main Building	16	12/14/2020	Detector kit	0.6
Madras Elementary	Main Building	17	12/14/2020	Detector kit	0.7
Madras Elementary	Main Building	18	12/14/2020	Detector kit	0.6
Madras Elementary	Main Building	25	12/14/2020	Detector kit	0.8
Madras Elementary	Main Building	26	12/14/2020	Detector kit	0.5
Madras Elementary	Main Building	GYM	12/14/2020	Detector kit	0.5
Madras Elementary	Main Building	GYM	12/14/2020	Detector kit	0.9
Madras Elementary	Main Building	GYM	12/14/2020	Detector kit	0.8
Madras Elementary	Main Building		12/14/2020	Detector kit	0.6
Madras Elementary	Main Building	GYM BLK	12/14/2020	Detector kit	<0.3
Madras Elementary	Main Building	19	12/14/2020	Detector kit	0.4
Madras Elementary	Main Building	20	12/14/2020	Detector kit	0.6
Madras Elementary	Main Building	21	12/14/2020	Detector kit	0.4
Madras Elementary	Main Building	22	12/14/2020	Detector kit	<0.3
Madras Elementary	Main Building	23	12/14/2020	Detector kit	0.4
Madras Elementary	Main Building	PRINCIPLE	12/14/2020	Detector kit	0.3
Madras Elementary	Main Building	ADMIN	12/14/2020	Detector kit	0.9

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Madras Elementary	Main Building	WORK	12/14/2020	Detector kit	0.5
Madras Elementary	Main Building	HEALTH	12/14/2020	Detector kit	0.6
Madras Elementary	Main Building	2	12/14/2020	Detector kit	1.0
Madras Elementary	Main Building	3	12/14/2020	Detector kit	0.4
Madras Elementary	Main Building	4	12/14/2020	Detector kit	0.7
Madras Elementary	Main Building	CAFE	12/14/2020	Detector kit	0.8
Madras Elementary	Main Building	CAFE	12/14/2020	Detector kit	0.7
Madras Elementary	Main Building	CAFE DUP	12/14/2020	Detector kit	0.8
Madras Elementary	Main Building	LIBRARY	12/14/2020	Detector kit	<0.3
Madras Elementary	Main Building	LIBRARY	12/14/2020	Detector kit	0.4
Madras Elementary	Main Building	5	12/14/2020	Detector kit	0.6
Madras Elementary	Main Building	6	12/14/2020	Detector kit	0.5
Madras Elementary	Main Building	7	12/14/2020	Detector kit	0.8
Madras Elementary	Main Building	8	12/14/2020	Detector kit	1.0
Madras Elementary	Main Building	9	12/14/2020	Detector kit	0.9
Madras Elementary	Main Building	10	12/14/2020	Detector kit	0.8
Madras Elementary	Main Building	11	12/14/2020	Detector kit	0.8
Madras Elementary	Main Building	12	12/14/2020	Detector kit	0.6
Madras Elementary	Main Building	24	12/14/2020	Detector kit	0.4
Madras Elementary	Main Building	BASEMENT DUP	12/14/2020	Detector kit	0.7

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Madras Elementary	Main Building	LIBRARY DUP	12/14/2020	Detector kit	<0.3
Madras Elementary	Main Building	ADMIN DUP	12/14/2020	Detector kit	0.4
Madras Elementary	Main Building	I3	12/14/2020	Detector kit	1.0
Madras Elementary	Main Building	OFFICE	12/14/2020	Detector kit	1.1
Buff Elementary	Main Building	ADMIN	12/14/2020	Detector kit	0.9
Buff Elementary	Main Building	PRINCIPAL	12/14/2020	Detector kit	0.8
Buff Elementary	Main Building	OFFICE	12/14/2020	Detector kit	0.8
Buff Elementary	Main Building	WORK	12/14/2020	Detector kit	0.9
Buff Elementary	Main Building	BREAK	12/14/2020	Detector kit	1.0
Buff Elementary	Main Building	GYM	12/14/2020	Detector kit	0.8
Buff Elementary	Main Building	GYM	12/14/2020	Detector kit	0.8
Buff Elementary	Main Building	GYM	12/14/2020	Detector kit	0.9
Buff Elementary	Main Building	GYM DUP	12/14/2020	Detector kit	0.8
Buff Elementary	Main Building	GYM BLK	12/14/2020	Detector kit	<0.3
Buff Elementary	Main Building	CAFE	12/14/2020	Detector kit	0.7
Buff Elementary	Main Building	CAFE	12/14/2020	Detector kit	0.9
Buff Elementary	Main Building	CAFE DUP	12/14/2020	Detector kit	1.0
Buff Elementary	Main Building	PE OFFICE	12/14/2020	Detector kit	0.7
Buff Elementary	Main Building	A120	12/14/2020	Detector kit	0.4
Buff Elementary	Main Building	A121	12/14/2020	Detector kit	0.8

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Buff Elementary	Main Building	A122	12/14/2020	Detector kit	<0.3
Buff Elementary	Main Building	A145	12/14/2020	Detector kit	0.9
Buff Elementary	Main Building	A141	12/14/2020	Detector kit	0.9
Buff Elementary	Main Building	B120	12/14/2020	Detector kit	0.5
Buff Elementary	Main Building	B121	12/14/2020	Detector kit	<0.3
Buff Elementary	Main Building	B102	12/14/2020	Detector kit	<0.3
Buff Elementary	Main Building	B101	12/14/2020	Detector kit	0.8
Buff Elementary	Main Building	B106	12/14/2020	Detector kit	1.2
Buff Elementary	Main Building	B122	12/14/2020	Detector kit	1.0
Buff Elementary	Main Building	B140	12/14/2020	Detector kit	0.9
Buff Elementary	Main Building	B141	12/14/2020	Detector kit	0.7
Buff Elementary	Main Building	B144	12/14/2020	Detector kit	1.4
Buff Elementary	Main Building	B150	12/14/2020	Detector kit	2.7
Buff Elementary	Main Building	I2	12/14/2020	Detector kit	0.9
Buff Elementary	Main Building	B152	12/14/2020	Detector kit	1.2
Buff Elementary	Main Building	B162	12/14/2020	Detector kit	0.9
Buff Elementary	Main Building	C110	12/14/2020	Detector kit	0.9
Buff Elementary	Main Building	C111	12/14/2020	Detector kit	1.0
Buff Elementary	Main Building	C113	12/14/2020	Detector kit	1.0
Buff Elementary	Main Building	C114	12/14/2020	Detector kit	1.4

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Buff Elementary	Main Building	C115	12/14/2020	Detector kit	0.8
Buff Elementary	Main Building	C116	12/14/2020	Detector kit	1.0
Buff Elementary	Main Building	C120	12/14/2020	Detector kit	1.4
Metolius Elementary	Main Building	OFFICE	12/15/2020	Detector kit	0.4
Metolius Elementary	Main Building	GYM	12/15/2020	Detector kit	0.3
Metolius Elementary	Main Building	GYM	12/15/2020	Detector kit	0.6
Metolius Elementary	Main Building	GYM DUP	12/15/2020	Detector kit	0.4
Metolius Elementary	Main Building	GYM BLANK	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	7	12/15/2020	Detector kit	0.4
Metolius Elementary	Main Building	8	12/15/2020	Detector kit	0.6
Metolius Elementary	Main Building	9	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	12	12/15/2020	Detector kit	0.5
Metolius Elementary	Main Building	13	12/15/2020	Detector kit	0.4
Metolius Elementary	Main Building	10	12/15/2020	Detector kit	0.3
Metolius Elementary	Main Building	11	12/15/2020	Detector kit	0.5
Metolius Elementary	Main Building	11 DUP	12/15/2020	Detector kit	0.5
Metolius Elementary	Main Building	LIB OFF	12/15/2020	Detector kit	0.8
Metolius Elementary	Main Building	14	12/15/2020	Detector kit	0.3
Metolius Elementary	Main Building	16	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	17	12/15/2020	Detector kit	<0.3

Jefferson County School District Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Metolius Elementary	Main Building	PRINCIPAL	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	NURSE	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	ERC	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	5	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	6	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	4	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	3	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	2	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	GYM	12/15/2020	Detector kit	<0.3
Metolius Elementary	Main Building	17 BLK	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CONF	12/15/2020	Detector kit	0.4
Jefferson County Middle School	Main Building	112	12/15/2020	Detector kit	0.3
Jefferson County Middle School	Main Building	COMPUTER	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	MEDIA	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	MEDIA	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	MEDIA	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	MEDIA DUP	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	RECEPTION	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	18	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	180	12/15/2020	Detector kit	<0.3

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Jefferson County Middle School	Main Building	180 DUP	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	179	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	177	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	176	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	174	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	173	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	172	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	SPECIAL ED	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	SPECIAL ED	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 114	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 116	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 118	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 120	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 122	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 123	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 124	12/15/2020	Detector kit	0.3
Jefferson County Middle School	Main Building	CLASS 125	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 126	12/15/2020	Detector kit	0.4
Jefferson County Middle School	Main Building	CLASS 119	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 117	12/15/2020	Detector kit	<0.3

Jefferson County School District Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Jefferson County Middle School	Main Building	CLASS 139	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	MUSIC	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	COMMONS	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	COMMONS	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	COMMONS	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	COMMONS DUP	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	COMMONS BLANK	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	127	12/15/2020	Detector kit	0.5
Jefferson County Middle School	Main Building	129	12/15/2020	Detector kit	0.4
Jefferson County Middle School	Main Building	129 DUP	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	132	12/15/2020	Detector kit	0.4
Jefferson County Middle School	Main Building	134	12/15/2020	Detector kit	0.4
Jefferson County Middle School	Main Building	130	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	136	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	138	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 141	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 137	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 135	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 133	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	CLASS 133 DUP	12/15/2020	Detector kit	<0.3

Jefferson County School District Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Jefferson County Middle School	Main Building	I42	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	WRESTLE	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	WRESTLE	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	WRESTLE DUP	12/15/2020	Detector kit	0.3
Jefferson County Middle School	Main Building	SMALL GYM	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	SMALL GYM	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	SMALL GYM DUP	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	GYM	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	GYM	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	GYM	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	GYM	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	GYM	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	GYM DUP	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	GYM BLANK	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	I43	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	I43 DUP	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	I44	12/15/2020	Detector kit	<0.3
Jefferson County Middle School	Main Building	I44 BLK	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	LIBRARY	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	LIB DUB	12/15/2020	Detector kit	0.5

Jefferson County School District Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Warm Springs K-8	Main Building	DISCOVER	12/15/2020	Detector kit	0.4
Warm Springs K-8	Main Building	DISCOVER	12/15/2020	Detector kit	0.3
Warm Springs K-8	Main Building	DISCOVER DUB	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	LIFE	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	LIFE DUB	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	ES	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	IS	12/15/2020	Detector kit	0.8
Warm Springs K-8	Main Building	WRK	12/15/2020	Detector kit	0.3
Warm Springs K-8	Main Building	SPEECH	12/15/2020	Detector kit	0.4
Warm Springs K-8	Main Building	COMMONS	12/15/2020	Detector kit	0.4
Warm Springs K-8	Main Building	COMMONS	12/15/2020	Detector kit	0.6
Warm Springs K-8	Main Building	COMMONS	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	COMMONS DUP	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	COMMONS BLK	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	MUSIC	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	MUSIC	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	GYM	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	GYM	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	GYM	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	GYM	12/15/2020	Detector kit	0.6

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Warm Springs K-8	Main Building	GYM DUP	12/15/2020	Detector kit	0.4
Warm Springs K-8	Main Building	GYM BLK	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	MAT ROOM	12/15/2020	Detector kit	0.4
Warm Springs K-8	Main Building	MAT ROOM	12/15/2020	Detector kit	0.4
Warm Springs K-8	Main Building	C1	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	C2	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	C3	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	C4	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	C5	12/15/2020	Detector kit	0.7
Warm Springs K-8	Main Building	C6	12/15/2020	Detector kit	0.4
Warm Springs K-8	Main Building	C7	12/15/2020	Detector kit	0.8
Warm Springs K-8	Main Building	C9	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	C10	12/15/2020	Detector kit	0.9
Warm Springs K-8	Main Building	C11	12/15/2020	Detector kit	0.8
Warm Springs K-8	Main Building	C12	12/15/2020	Detector kit	0.4
Warm Springs K-8	Main Building	C13	12/15/2020	Detector kit	0.9
Warm Springs K-8	Main Building	COMMUNITY	12/15/2020	Detector kit	0.3
Warm Springs K-8	Main Building	STAFF	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	ADMIN	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	PRINCIPAL	12/15/2020	Detector kit	<0.3

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Warm Springs K-8	Main Building	WORK	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	OFFICE	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	RECEPTION	12/15/2020	Detector kit	0.3
Warm Springs K-8	Main Building	A1	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	A2	12/15/2020	Detector kit	1.2
Warm Springs K-8	Main Building	A3	12/15/2020	Detector kit	0.8
Warm Springs K-8	Main Building	A4	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	A5	12/15/2020	Detector kit	0.6
Warm Springs K-8	Main Building	A7	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	A8	12/15/2020	Detector kit	0.9
Warm Springs K-8	Main Building	A9	12/15/2020	Detector kit	1.0
Warm Springs K-8	Main Building	A10	12/15/2020	Detector kit	0.6
Warm Springs K-8	Main Building	A11	12/15/2020	Detector kit	1.2
Warm Springs K-8	Main Building	A12	12/15/2020	Detector kit	1.7
Warm Springs K-8	Main Building	LIBRARY	12/15/2020	Detector kit	<0.3
Warm Springs K-8	Main Building	C14	12/15/2020	Detector kit	0.8
Warm Springs K-8	Main Building	B1	12/15/2020	Detector kit	0.7
Warm Springs K-8	Main Building	B2	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	B3	12/15/2020	Detector kit	0.4
Warm Springs K-8	Main Building	B4	12/15/2020	Detector kit	0.7

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Warm Springs K-8	Main Building	B6	12/15/2020	Detector kit	0.5
Warm Springs K-8	Main Building	B7	12/15/2020	Detector kit	0.7
Warm Springs K-8	Main Building	B8	12/15/2020	Detector kit	0.6
Warm Springs K-8	Main Building	B9	12/15/2020	Detector kit	0.6
Warm Springs K-8	Main Building	B10	12/15/2020	Detector kit	0.6
Warm Springs K-8	Main Building	B11	12/15/2020	Detector kit	0.8
Warm Springs K-8	Main Building	B12	12/15/2020	Detector kit	1.0
Maintenance Office	Main Building	ELEC	12/14/2020	Detector kit	1.0
Maintenance Office	Main Building	ELEC	12/14/2020	Detector kit	0.8
Maintenance Office	Main Building	ELEC DUP	12/14/2020	Detector kit	1.0
Maintenance Office	Main Building	LIBRARY	12/14/2020	Detector kit	0.9
Maintenance Office	Main Building	OFFICE 1	12/14/2020	Detector kit	1.2
Maintenance Office	Main Building	OFFICE 2	12/14/2020	Detector kit	1.3
Maintenance Office	Main Building	RECEPTION	12/14/2020	Detector kit	1.0
Maintenance Office	Main Building	RECEPTION	12/14/2020	Detector kit	1.0
Maintenance Office	Main Building	RECEPTION BLANK	12/14/2020	Detector kit	<0.3
Maintenance Office	Main Building	FOOD SERV	12/14/2020	Detector kit	2.6
Maintenance Office	Main Building	FOOD OFF	12/14/2020	Detector kit	1.1
Maintenance Office	Main Building	FOOD SERV DUP	12/14/2020	Detector kit	2.3
Maintenance Office	Main Building	TRANSPORTATION	12/14/2020	Detector kit	0.7

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Maintenance Office	Main Building	TRANSPORTATION ENTRY	12/14/2020	Detector kit	1.1
Westside Elementary	Main Building	7	12/15/2020	Detector kit	<0.3
Westside Elementary	Main Building	6	12/15/2020	Detector kit	<0.3
Westside Elementary	Main Building	5	12/15/2020	Detector kit	0.4
Westside Elementary	Main Building	FOYER DUP	12/15/2020	Detector kit	<0.3
Westside Elementary	Main Building	CAFE	12/15/2020	Detector kit	0.3
Westside Elementary	Main Building	CAFE	12/15/2020	Detector kit	0.3
Westside Elementary	Main Building	CAFE DUP	12/15/2020	Detector kit	<0.3
Westside Elementary	Main Building	K-3	12/15/2020	Detector kit	0.5
Westside Elementary	Main Building	K-3 DUP	12/15/2020	Detector kit	0.5
Westside Elementary	Main Building	K-2	12/15/2020	Detector kit	<0.3
Westside Elementary	Main Building	MUSIC	12/15/2020	Detector kit	0.5
Westside Elementary	Main Building	MUSIC	12/15/2020	Detector kit	0.6
Westside Elementary	Main Building	K-1	12/15/2020	Detector kit	0.4
Westside Elementary	Main Building	K-1	12/15/2020	Detector kit	0.5
Westside Elementary	Main Building	GYM	12/15/2020	Detector kit	0.8
Westside Elementary	Main Building	GYM	12/15/2020	Detector kit	0.6
Westside Elementary	Main Building	GYM	12/15/2020	Detector kit	0.6
Westside Elementary	Main Building	GYM	12/15/2020	Detector kit	0.6
Westside Elementary	Main Building	GYM DUP	12/15/2020	Detector kit	0.7

Jefferson County School District

Radon Testing Results

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- Twenty spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.

Site Name	Building Name	Room Description (per floor plan)	Date Sampled	Type of test	Results (pCi/L)
Westside Elementary	Main Building	RECEPTION	12/15/2020	Detector kit	0.5
Westside Elementary	Main Building		12/15/2020	Detector kit	0.4
Westside Elementary	Main Building	WORK	12/15/2020	Detector kit	0.5
Westside Elementary	Main Building	OFFICE	12/15/2020	Detector kit	0.4
Westside Elementary	Main Building	GYM BLANK	12/15/2020	Detector kit	<0.3
Westside Elementary	Main Building	FOYER	12/15/2020	Detector kit	0.6
Westside Elementary	Main Building	9	12/15/2020	Detector kit	0.3
Westside Elementary	Main Building	8	12/15/2020	Detector kit	<0.3
Westside Elementary	Main Building	10	12/15/2020	Detector kit	<0.3
Westside Elementary	Main Building	11	12/15/2020	Detector kit	0.3
Westside Elementary	Main Building	12	12/15/2020	Detector kit	<0.3
Westside Elementary	Main Building	13	12/15/2020	Detector kit	0.4
Westside Elementary	Main Building	LIBRARY	12/15/2020	Detector kit	<0.3
Westside Elementary	Main Building	LIBRARY	12/15/2020	Detector kit	<0.3
Westside Elementary	Main Building	LIB DUP	12/15/2020	Detector kit	0.4
Westside Elementary	Main Building	GYM BLK	12/15/2020	Detector kit	<0.3